



BOTTOM HOLE ASSURANCE, INC.

No. BH-43344-1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection
Email: BHAlnc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592
Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER: Hole Opener 3RD PARTY
RIG: CCS-G & WELL
PROJECT: Water Oil & Gas RC-51123
FACILITY/LOCATION: Shop
AUTHORIZED BY: Denovan P.O. JOB # 7829
INVOICE NO. 43344
DATE: 8/19/2021

Table with columns: Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Diameter, Pin Nose Diameter, Pin Roller Diameter, Pin Roll Width, Bevel Diameter, BSR, OK or Reject, Remarks, Connection Size, Counter Bore Length, Counter Bore Diameter, Bore Back Dia., Bore Back Lgth, Box Thread Length, Counterbore Wall Thickness, Bevel Diameter, BSR, OK or Reject, Remarks.

Remarks: Inspection as per Ds-1 Volume 4
Batch # Info: 20-B 20B065
Connection Inspection: Wet Flour M.P.I., Dry M.P.I., Residual
Body Inspection: Residual, AC Current, DC Current, Trans Insp, Wet M.P.-Control Strip
Body Dry M.P.I.: Residual, AC Current, DC Current, Trans Insp, Profile Gauge RSC OK
Backlight Inspection: Backlight Intensity 8250, Bath Mixture 025, White light 0.0
Liquid Penetrant Inspection: White light, Magnalux Developer SKD-S2, Magnalux Penetrant, SIL MFP2, 2-60D, 3rd Party: Lucas Brossard