



BOTTOM HOLE ASSURANCE, INC.
 Blacklight, Ultrasonic Well Thickness
 & Liquid Penetrant Inspection
 Email: BHAlnc@bottomholeassurance.com
 109 Citron Drive • Youngsville, LA 70592
 Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER: Hole Opener RIG: JBD PARTY
 PROJECT: Walter Oil & Gas RC-51123 FACILITY/LOCATION: Shop
 OCCS G & WELL: _____ AUTHORIZED BY: Donovan
 P.O. JOB #: 7829 INVOICE NO.: 43344
 DATE: 8/19/2021

Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	PIN								OK or Reject	Remarks	BOX				OK or Reject	Remarks												
								Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Ret. Width	Bevel Diameter	B S R			Connection Size	Counter Bore Length	Counter Bore Diameter	Float Bore Dia.			Bore Back Dia.	Float Bore Lgth	Bore Back Lgth	Box Thread Length	Well Thickness	Counterbore	Bevel Diameter	B S R				
05-16B-044-494,489,490	(3) Hinge Block Pin															OK																			
05-16B-020-072, -082, -090	(3) Cutter Arm															OK																			
05-220-035-010	Yoke															INT																			
XO-18-95-3	Float Sub	3.45	FL	FL	N/A		9 1/2									INT																			

Remarks: _____

Batch # Info: 20-B 28B065
 Connection Inspection: Wet Flour M.P.I. Dry M.P.I. Residual Wet Flour M.P.I. We. Lag Pen. Fluor Lin Pen. Long Insp. Trans Insp. AC Current DC Current Profile Gauge RSC OK

Body Inspection: Dry M.P.I. Residual Fluor Lin Pen. Long Insp. Trans Insp. AC Current DC Current

Body Dry M.P.I.: Residual Continuous

White Contrast: Long Insp. Trans Insp.

System Effectiveness: LP Competitive Block DC Current Wet M.P. Contact Strip

Job Information: LB _____ V _____ LB _____ D _____ P _____ LB _____

Signature: _____

Signature: Lucas Broussard
 Equipment Used From Unit # 29
 Mt. 21/2021
 PT

Liquid Penetrant Inspection: White Light _____
 Magnaflux Developer SLD-S2
 Batch # _____
 Magnaflux Penetrant (Check one) SHL-MP2 ZL-50D
 Batch # _____
 Dwell Time: _____ min