



BOTTOM HOLE ASSURANCE, INC.

BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic, Wall Thickness, & Liquid Penetrant Inspection

Blacklight, Ultrasonic, Wall Thickness, & Liquid Penetrant Inspection

CUSTOMER: HOLE OPENER INTERNATIONAL | 3RD PARTY | FACILITY/LOCATION: SHOP | PROJECT: BAKER HUGHES MALAYSIA / RA 10147 | AUTHORIZED BY: DONOVAN | P.O. JOB #: 103119 | INVOICE NO.: 43481 | DATE: 7/15/2021

Table with columns: Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin ID, Pin O.D., Box O.D., Connection Size, Pin Length, Pin Diameter, Pin Cylinder Diameter, Pin Nose Diameter, Pin Roller Diameter, Pin Neck Length, Bevel Diameter, BSR, OK or Reject, Remarks, Connection Size, Counter Bore Length, Counter Bore Diameter, Flat Bore Dia., Bore Back Dia., Flat Bore Length, Bore Back Length, Box Thread Length, Wall Thickness, Counterbore, Bevel Diameter, BSR, OK or Reject, Remarks.

Remarks: FULL BODY INSP AS PER DS-1 VOL 4

Batch # Info, Connection Inspection, Body Inspection, Body Dry MPI, Blacklight Inspection, Equipment / Inspector Information, Liquid Penetrant Inspection, Job Information, Signature: TANNER BLANCHARD